





A




B



Aa		8x20	x8
Ba		8x30	x38
Ca		7x30	x6
E		7x50	x4
Ea		M6x35	x2
Fa		M6x8x15x15	x2
Ga		7x34	x18
Ha		15x12	x18
G		5x38	x31
Ja		5x50	x4
Ka		21x21x16	x2
La		3,5x15	x4
Ma		3x20	x4

Q		3,5x40	x19
Oa		3,5x16	x21
J		4x30	x4
Ra		D19x6	x4
V		D26	x2
Qa		D35	x4
W		11/5,8x6,5	x4
WS		11/6,2x9	x8
T		4mm	x2
Y		350	x1



1



Aa		8x20	x8
Ba		8x30	x26

2a



A



Ca		7x30	x6
----	---	------	----

2b



B




Ca		7x30	x6
----	---	------	----

3a



A



Y		350	x1
W		11/5,8x6,5	x4

3b




B



Y		350	x1
W		11/5,8x6,5	x4


4a

A




E		7x50	x2
---	---	------	----

4b




E		7x50	x2
---	---	------	----

5a





Ga		7x34	x4
----	---	------	----

5b







Ga		7x34	x4
----	---	------	----



7

A






Ga



7x34

x4

8




Ha



15x12


x4

9






G		5x38	x2
---	---	------	----

10





J		4x30	x2
Ka		21x21x16	x2
La		3,5x15	x4
Ha		15x12	x2


11




Ma		3x20	x4
Y		350	x1

12





E		7x50	x2
V		D26	x2
Oa		3,5x16	x4

13





Fa		M6x8x15	x2
Ea		M6x35	x2

14




40 - 747x70x17mm 5pcs.




Ra		D19x12	x2
G		5x38	x3
Ja		5x50	x2
Q		3,5x40	x5





15



41 - 780x90x17mm 2pcs.





42 - 780x70x17mm 4pcs.




Ra		D19x6	x2
Oa		3,5x16	x12
G		5x38	x4
Ja		5x50	x2


16



38 - 590x70x17mm 3pcs.




39 - 590x70x17mm 2pcs.




Oa		3,5x16	x5
G		5x38	x10



17






1.



2.




18




Q		3,5x40	x14
---	---	--------	-----

19




Ba		8x30	x8
----	---	------	----

20





Ga		7x34	x4
----	---	------	----

21





Ha		15x12	x4
----	---	-------	----

22





G		5x38	x4
J		4x30	x2

23




Ga		7x34	x4
----	---	------	----

24




Ba		8x30	x4
----	---	------	----

25





G		5x38	x4
---	---	------	----

26



Ha		15x12	x4
----	---	-------	----

27



WS		11/6,2x9	x8
Qa		D35	x4