



16215647

1600x420x750

1. Attach the leg to the metal bracket
2. Attach a metal bracket with the foot to the product



				SW 4 mm		F
						
						1x
	A	M8x25	B	M6x16	C	115x115x5 mm
						
				D		SW 5 mm
						E
						
						1x
2x		2x	8x	2x		