




Service • Assistenza • Dienstverlening • Serwis

Servis • Szerviz • Сервисная служба

Name • Nom • Nome • Naam Nazwa • Jméno • Názov • Név Denumire • Ísim • Название	
Nr. • No. • N° • Номер • Č • Sz	
Typ • Type • Тип • Típus • Tipo Тип	



A		8x40	x16
B		10x40	x30
C		7x60	x9
D		D35	x6
E		7x34	x17
F		15x12	x17
G		M6x60	x4
H		M6x10x13	x4
J		3,5x16	x2
K		4x20	x2







L		3,5x40	x6
M		28x17x15	x2
N		D12x18	x2
P		1,2x20	x18
Q		D25x4	x6
R		D35x9	x2
S		D8x20x10	x2
T		D8xD28x20	x2
V		4mm	x1

A		8x40	x16
E		7x34	x8
F		15x12	x8
X		D26	x8

J		3,5x16	x16
P		1,2x20	x24
Y		D5x16	x8
Z			x1

A		8x40	x12
E		7x34	x12
F		15x12	x12
X		D26	x12



J		3,5x16	x24
L		3,5x40	x12
M		28x17x15	x4
K		4x20	x4



A		8x40	x16
B		10x40	x30
C		7x60	x9
D		D35	x6
E		7x34	x17
F		15x12	x17
G		M6x60	x4
H		M6x10x13	x4
J		3,5x16	x2
K		4x20	x2



L		3,5x40	x6
M		28x17x15	x2
N		D12x18	x2
P		1,2x20	x25
Q		D25x4	x6
R		D35x9	x2
S		M8x20x10	x2
T		M8xD28x20	x2
V		4mm	x1

1




A		8x40	x16
---	---	------	-----

2





B		10x40	x30
---	---	-------	-----

3




4mm




C		7x60	x6
---	---	------	----


4



D		D35	x2
---	---	-----	----


5



D		D35	x2
R		D35x9	x2





Q		D25x4	x2
---	---	-------	----

6







E		7x34	x16
---	---	------	-----

7







F		15x12	x8
---	---	-------	----

8



F		15x12	x8
---	---	-------	----

9





Q		D35	x4
N		D35x9	x2

P		1,2x20	x18
---	---	--------	-----

10



4mm



E

6

D




D

9



D		D35	x2
E		7x34	x1

11






2x

15

S		D8x20x10	x2
---	--	----------	----

12

~17mm




2x

15

T		D8xD28x20	x2
---	--	-----------	----


13



G		M6x60	x4
H		M6x10x13	x4

C		10x40	x3
F		15x12	x1


14



K		4x20	x2
J		3,5x16	x2


M		28x17x15	x2
---	---	----------	----

15




L		3,5x40	x6
---	---	--------	----

2x




A		8x40	x16
E		7x34	x8
F		15x12	x8
X		D26	x8
J		3,5x16	x16
P		1,2x20	x24
Y		D5x16	x8
Z			x1

16




A		8x40	x16
---	---	------	-----

17



E		7x34	x8
---	---	------	----

18




2x

F		15x12	x8
---	---	-------	----




19

2x



20



2x



P		1,2x20	x24
---	---	--------	-----

21



2x




X		D26	x8
J		3,5x16	x16

22

2x





Y		D5x16	x8
---	---	-------	----






A		8x40	x12
E		7x34	x12
F		15x12	x12
X		D26	x12
J		3,5x16	x24
L		3,5x40	x12
M		28x17x15	x4
K		4x20	x4

23







A		8x40	x12
---	--	------	-----

24






E		7x34	x12
---	--	------	-----

25






F		15x12	x12
---	--	-------	-----

26






L		3,5x40	x12
---	--	--------	-----

27



X		D26	x12
J		3,5x16	x24

28



M		28x17x15	x4
K		4x20	x4