

car trend

Flachbalken- wischer



2 Stück



2 Stück

UB8+



ALFA ROMEO

145 [930]	04.97 – 12.00	UB7+
146 [930]	04.97 – 12.00	UB7+
156 Berlina [932]	10.97 – 12.05	UB8+
156 Sport Wagon [932]	06.00 – 12.05	UB8+
166 [936]	07.98 – 10.07	UB4+
Giulietta [940]	04.10 →	UB9+
Mito [955]	05.08 →	UB10+

AUDI

80 [8C2;B4]	09.91 – 05.95	UB5+
80 Avant [8C5;B4]	03.92 – 07.95	UB5+
A3 [8L1]	09.96 – 06.03	UB4+
A3 [8P1]	05.03 – 11.04	UB1+
A3 [8P1]	12.04 – 03.13	UB9+
A3 Sportback [8PA]	09.04 – 11.04	UB1+
A3 Sportback [8PA]	12.04 – 03.13	UB9+
A4 [8D2;B5]	11.94 – 09.01	UB5+
A4 [8E2;B6]	10.00 – 03.01	UB5+
A4 Avant [8D5;B5]	11.94 – 09.01	UB5+
A6 [4A2;C4]	06.94 – 10.97	UB8+
A6 [4B2;C5]	04.97 – 05.01	UB8+
A6 Avant [4A5;C4]	06.94 – 10.97	UB8+
A6 Avant [4B5;C5]	04.97 – 05.01	UB8+
A6 Avant Allroad [4BH;C5]	05.00 – 12.00	UB8+
A8 [4D2;D2]	06.94 – 09.02	UB8+
Cabriolet [8G7;B4]	06.91 – 08.00	UB8+
Coupé [89;B3]	11.88 – 12.95	UB8+
RS3 Sportback [8PA]	01.11 – 12.12	UB9+
RS4 Avant [8D5;B5]	05.00 – 09.01	UB5+
RS6 [4B4]	07.02 – 04.04	UB8+
RS6 Avant [4B6]	05.02 – 09.04	UB8+
S3 [8L1]	08.98 – 06.03	UB4+
S3 [8P1]	11.06 – 03.13	UB9+



AUDI

S3 Sportback [8PA]	07.08–03.13	UB9+
S4 [8D2;B5]	10.97–09.01	UB5+
S4 Avant [8D5;B5]	10.97–09.01	UB5+
S6 [4A2;C4]	06.94–10.97	UB8+
S6 [4B;C5]	09.99–05.04	UB8+
S6 Avant [4A5;C4]	06.94–10.97	UB8+
S6 Avant [4B;C5]	09.99–01.05	UB8+
S8 [4D2]	09.96–01.03	UB8+
TT Coupé [8N3]	05.03–06.06	UB5+
TT Roadster [8N9]	05.03–06.06	UB5+

BMW

M3 [F80]	06.14 →	UB9+
Serie 3 [E36]	09.90–12.98	UB5+
Serie 3 [E46]	04.98–04.05	UB1+
Serie 3 [E90]	09.09–08.13	UB9+
Serie 3 [F30]	02.12 →	UB9+
Serie 3 Cabrio [E36]	03.93–12.99	UB5+
Serie 3 Cabrio [E46]	03.00–08.06	UB1+
Serie 3 Compact [E36]	03.94–09.00	UB3+
Serie 3 Compact [E46]	06.01–12.04	UB1+
Serie 3 Coupé [E36]	03.91–12.99	UB5+
Serie 3 Coupé [E46]	04.98–05.06	UB1+
Serie 3 GT [F34]	06.13 →	UB9+
Serie 3 Touring [E36]	03.95–12.99	UB5+
Serie 3 Touring [E46]	10.98–09.05	UB1+
Serie 3 Touring [E91]	09.09–05.13	UB9+
Serie 3 Touring [F31]	09.12 →	UB9+
X1 [E84]	10.09–06.15	UB9+
X3 [E83]	01.04–08.10	UB8+





BMW

X5 [F15;F85]	11.13 →	UB1+
X6 [F16;F86]	11.14 →	UB1+
Z3 [E36/7]	03.95–09.02	UB3+
Z3 Coupé [E36/8]	09.97–06.02	UB3+

CADILLAC

ATS	09.12 →	UB7+
CTS	09.02–09.07	UB8+
CTS	09.07–08.10	UB7+
Escalade	09.01–08.06	UB8+
Escalade	09.09–08.13	UB8+
SRX	09.03–08.09	UB8+
SRX	09.09 →	UB10+

CHEVROLET

Avalanche	09.01–08.06	UB8+
Aveo [KL1T,T300]	06.11 →	UB10+
Aveo Hatchback [KL1T,T300]	06.11 →	UB10+
Captiva [KL1C,C100]	10.06–02.11	UB2+
Captiva [KL1C,C140]	04.11 →	UB2+
Epica [V250]	06.06–12.11	UB8+
Evanda [KL1L,V200]	02.03–09.06	UB8+
Lacetti [KL1N,J200]	02.05–04.13	UB7+
Lanos	01.04 →	UB3+
Malibu [KL1G,V300]	03.12–12.15	UB1+
Nubira [KL1N,J200]	02.05–04.13	UB7+
Nubira Station Wagon [KL1N,J200]	02.05–04.13	UB7+
Optra [J200]	09.02–12.14	UB7+
Optra Hatchback [J200]	09.02–12.14	UB7+
Orlando	10.10 →	UB1+
Prizm	01.89–08.02	UB6+
Rezzo [KL1U,U100]	02.05–05.09	UB1+
Silverado 1500	09.06–08.07	UB8+
Suburban 1500	09.00–08.02	UB8+



CHEVROLET

Tahoe	09.99–12.06	UB8+
TrailBlazer	09.01–08.09	UB8+

CHRYSLER

300M [LH]	09.98–12.04	UB1+
Crossfire [ZH]	09.03–08.08	UB8+
Neon [PL]	06.94–06.99	UB4+
Neon [PL]	09.99–12.05	UB7+
Neon Coupé [PL]	09.95–06.99	UB4+
PT Cruiser [PT]	06.00–12.10	UB5+
PT Cruiser Cabrio [PT]	09.00–12.10	UB5+
Sebring [JR]	09.00–08.06	UB8+
Sebring Convertible [JR]	01.01–09.09	UB8+
Stratus [JA]	08.95–04.01	UB8+
Stratus [JX]	08.96–12.99	UB8+
Stratus Cabrio [JA]	08.95–04.01	UB8+
Stratus Cabrio [JX]	08.96–12.99	UB8+

CITROËN

Berlingo [B9]	05.08 →	UB10+
Berlingo [M49]	07.96–11.02	UB8+
Berlingo [M59]	11.02–10.11	UB8+
C3 III [B618]	07.16 →	UB10+
C3-Pluriel [A42]	05.03–10.12	UB4+
Jumper [U5,23]	02.94–05.06	UB8+
Saxo [S8]	02.96–09.03	UB6+
Xantia [X2]	10.97–12.01	UB1+
Xantia Break [X2]	12.97–12.01	UB1+
XM [Y3,Y4]	05.89–10.00	UB8+
Xsara [N6,N7]	07.97–12.05	UB8+
Xsara Break [N6,N7]	10.97–03.10	UB8+
Xsara Coupé [N6,N7]	07.97–12.05	UB8+





DACIA

Duster [HS]	10.09–11.14	UB3+
Logan I [LS]	07.04 →	UB3+
Logan II [L8]	08.12–02.15	UB8+
Logan MCV I [KS/FS]	01.07 →	UB3+
Logan MCV II [K8]	03.13–02.15	UB8+
Logan Pick-Up [US]	01.07 →	UB3+
Sandero I [BS]	06.08 →	UB3+
Sandero II [B8]	08.12–02.15	UB8+
Super Nova	10.00–09.03	UB3+

DAEWOO

Evanda	03.03–01.05	UB8+
Gentra	09.05 →	UB7+
Lacetti [KLAN]	03.04–01.05	UB7+
Lanos [KLAT]	11.96–09.03	UB3+
Lanos Hatchback [KLAT]	11.96–09.03	UB3+
Leganza [KLAV,V100]	03.97–12.02	UB8+
Nubira [KLAJ,J100]	09.97–09.99	UB3+
Nubira [KLAN,J200]	10.99–01.05	UB7+
Nubira Hatchback [KLAJ,J100]	09.97–09.99	UB3+
Nubira Station Wagon [KLAJ,J100]	09.97–09.99	UB3+
Nubira Station Wagon [KLAN,J200]	08.99–01.05	UB7+
Rezzo [KLAU]	09.00–01.05	UB1+
Sens [TF698]	01.02 →	UB3+

DAIHATSU

Gran Move [G3]	11.96–07.02	UB4+
Materia	09.06 →	UB6+
Terios [J2]	01.06 →	UB4+

DODGE

Caliber [P3]	01.06–08.09	UB2+
Durango [WD]	09.10–08.15	UB8+
Magnum [LX]	09.04–08.08	UB8+
Nitro [KA]	09.06–08.11	UB3+



FIAT

500L [199..,CFA]	09.12 →	UB10+
Barchetta [183..]	01.95–02.05	UB3+
Brava [182..]	10.95–12.01	UB8+
Bravo [182..]	10.95–09.01	UB8+
Bravo [198]	03.07–12.14	UB9+
Cinquecento [170..]	07.91–07.98	UB3+
Croma [154..]	07.90–12.96	UB6+
Doblo [223..]	07.00–08.16	UB4+
Doblo Cargo [223..]	07.00–08.16	UB4+
Ducato [230;231;232;234]	03.94–03.02	UB8+
Ducato [243;244;245;247]	04.02–12.11	UB8+
Egea	11.15 →	UB10+
Freemont [JC]	06.11–12.15	UB1+
Fullback	05.16 →	UB4+
Grande Punto [199..]	10.05–12.11	UB10+
Idea [350]	01.04–12.05	UB2+
Linea [323]	03.07 →	UB10+
Marea [185..]	10.96–12.02	UB7+
Marengo [285..]	01.97–09.02	UB7+
Panda [169..]	10.03–12.12	UB2+
Punto [176..]	08.93–08.99	UB2+
Punto [188..]	07.99–12.10	UB4+
Punto [199..]	01.12 →	UB10+
Punto Cabrio [176..]	04.94–08.99	UB2+
Punto Evo [199..]	10.09–12.12	UB10+
Punto Grande [199..]	10.05–12.11	UB10+
Punto GT [176..]	08.93–08.99	UB2+
Punto VAN [276..]	05.97–08.99	UB2+
Punto VAN [288..]	05.99–12.10	UB4+
Seicento [187..]	03.98–12.10	UB3+
Stilo [192..]	10.01–06.05	UB4+
Stilo Multi Wagon [192..]	10.02–06.05	UB4+
Tipo [356]	11.15 →	UB10+
Tipo Hatchback [357]	11.15 →	UB10+
Tipo Station Wagon [358]	06.16 →	UB10+





FORD

Cougar	08.98–12.00	UB8+
Festiva	01.93–10.00	UB6+
Fiesta IV/V [96]	10.95–12.02	UB3+
Fiesta IV/V Courier [96]	10.95–12.02	UB3+
Fiesta VII [08]	07.08–11.12	UB10+
Fiesta VII [13]	11.12 →	UB10+
Focus I [99]	08.98–05.05	UB7+
Focus I Sedan [99]	08.98–05.05	UB7+
Focus I Turnier [99]	11.98–05.05	UB7+
Maverick [1EZ,1N2]	10.00–01.07	UB3+
Maverick [94,96]	06.93–12.98	UB5+
Mondeo I [93]	01.93–07.96	UB5+
Mondeo I Sedan [93]	01.93–07.96	UB5+
Mondeo I Turnier [93]	04.93–07.96	UB5+
Mondeo II [97]	08.96–09.00	UB5+
Mondeo II Sedan [97]	08.96–09.00	UB5+
Mondeo II Turnier [97]	08.96–09.00	UB5+
Mondeo III [01]	10.00–03.07	UB8+
Mondeo III Sedan [01]	10.00–03.07	UB8+
Mondeo III Turnier [01]	10.00–03.07	UB8+
Mustang	09.04–02.09	UB8+
Probe	09.88–08.97	UB3+
Ranger [TKE]	09.11–08.15	UB2+
Streetka	12.02–12.05	UB3+
Tourneo Connect [02]	05.02–12.13	UB8+
Transit [95]	08.94–08.00	UB8+
Transit Connect [02]	05.02–12.13	UB8+
Transit Tourneo [95]	08.94–08.00	UB8+

HONDA

Accord Aerodeck [CB/CC/CD/CE]	09.93–06.98	UB8+
Accord Coupé [CB/CC/CD/CE]	01.92–12.01	UB8+
Accord Coupé [CG]	12.97–12.02	UB1+
Accord Hatchback [CG/CH/CL]	10.98–02.03	UB7+
Accord Sedan [CA/CB/CD]	01.90–12.99	UB8+
Accord Sedan [CC/CE/CF]	03.93–10.98	UB8+
Accord Sedan [CG/CH/CL]	10.98–02.03	UB7+
Civic Aerodeck [MB/MC]	03.98–02.01	UB6+
Civic Coupé [EK]	05.01–12.04	UB4+
Civic CRX [EG/EH]	03.92–12.98	UB6+
Civic Fastback [MA]	09.94–01.97	UB6+



HONDA

Civic Fastback [MB/MC]	09.94–02.01	UB6+
Civic Hatchback [EG/EH]	10.91–09.95	UB6+
Civic Hatchback [EJ/EK]	10.95–02.01	UB6+
Civic Sedan [EG/EH]	10.91–09.95	UB6+
Civic Sedan [EJ/EK]	10.95–02.01	UB6+
Civic Sedan [ES]	02.01–01.06	UB4+
CR-V [KL]	07.03 →	UB4+
CR-V [RD]	10.95–07.02	UB3+
CR-V [RD]	07.02–09.06	UB5+
Insight Coupé [ZE]	01.00–12.06	UB6+
Integra Type R [DC]	01.98–10.01	UB6+
Legend	04.98–12.04	UB6+
Logo	09.96–06.01	UB6+
NSX Coupé [NA]	06.90–12.05	UB3+
Pilot [YF]	01.09–08.15	UB8+
Prelude [BB]	02.92–09.96	UB4+

HYUNDAI

Accent [LC]	05.99–06.06	UB6+
Accent [X3]	04.94–07.99	UB6+
Accent Hatchback [LC]	08.99–06.06	UB6+
Accent Hatchback [X3]	07.94–07.99	UB6+
Coupé [FX]	07.96 →	UB4+
Coupé [GK]	10.01–08.09	UB4+
Coupé [RD]	05.96–04.02	UB4+
Elantra [HD]	09.05 →	UB6+
Elantra [J1]	10.90–04.95	UB6+
Elantra [J2]	05.95–09.00	UB6+
Elantra [XD]	06.00–09.06	UB6+
Elantra Hatchback [XD]	06.00–09.06	UB6+
Equus [VI]	10.09–11.12	UB9+
Equus [VI]	12.12 →	UB1+
Excel [X3]	07.94–07.99	UB6+
Excel Hatchback [X3]	11.95–07.99	UB6+
Genesis Coupe [BK]	11.08–03.16	UB1+
Genesis Sedan [BH]	05.11–03.16	UB1+
Grandeur [TG]	07.05 →	UB1+
i20 [PB]	12.08 →	UB2+





HYUNDAI

i30 [FD]	09.07–03.10	UB9+
i30 CW [FD]	02.08–03.10	UB9+
ix35 [LM/EL]	01.10 →	UB2+
Lantra [J1]	10.90–04.95	UB6+
Lantra [J2]	05.95–09.00	UB6+
Lantra Kombi [J2]	05.95–09.00	UB6+
Pony [X3]	07.94–07.99	UB6+
Santa Fe [SM]	09.99–12.05	UB8+
Sonata II [Y3]	11.93–04.98	UB3+
Sonata III [EF]	03.98–03.01	UB6+
Sonata IV [EF]	04.01–01.05	UB8+
Terracan [HP]	01.01–10.06	UB8+
Tucson [JM]	08.04–03.10	UB2+
Verna [LC]	07.99–03.06	UB6+
Verna [MC]	10.06–05.11	UB4+
XG [F]	12.98–12.05	UB8+

INFINITI

FX [S50]	11.02–08.08	UB8+
FX [S51]	07.08–12.14	UB1+
M-Serie [Y50]	07.06–05.10	UB1+
Q30	11.15 →	UB9+
QX30	09.16 →	UB9+
QX4 [JR50]	09.96–08.03	UB8+
QX50	10.13 →	UB2+
QX56 [Z62]	03.10–06.14	UB1+
QX70 [S51]	11.13 →	UB1+

ISUZU

D-MAX	05.02 →	UB7+
-------	---------	------

JAGUAR

S-Type [CCX]	10.98–04.02	UB8+
XK 8 Convertible [QDV]	03.96–02.09	UB5+
XK 8 Coupé [QEV]	03.96–02.09	UB5+
XKR 8 Convertible [QDV]	03.96–02.09	UB5+
X-Type [CF1]	03.01–06.10	UB7+
X-Type Estate [CF1]	03.03–12.09	UB7+

JEEP

Cherokee [KJ]	03.01–12.07	UB3+
Cherokee [KK]	01.08 →	UB3+



JEEP

Compass [MK,PK]	10.06 →	UB8+
Grand Cherokee [WG]	09.00–12.04	UB5+
Grand Cherokee [WH]	03.05–10.11	UB5+
Grand Cherokee [WK]	09.03 →	UB5+
Grand Cherokee [WK2]	09.10 →	UB8+
Grand Cherokee [ZG]	09.92–04.99	UB3+
Liberty [KK]	09.07 →	UB3+
Patriot [MK]	10.06 →	UB5+

KIA

Cee'd [ED/FF2]	11.06–06.09	UB9+
Cee'd Sporty Wagon [ED/FF2]	09.07–06.09	UB9+
Cerato [TD]	12.08 →	UB1+
Cerato [FE]	03.04–11.09	UB2+
Cerato Hatchback [FE]	03.04–11.09	UB2+
Cerato Koup [TD]	08.10 →	UB1+
Ceres	06.99 →	UB4+
Clarus [GC]	05.96–11.01	UB4+
Clarus II Kombi [GC]	06.98–11.01	UB4+
Joice [MT]	08.99–03.03	UB4+
K 2500	09.01–12.06	UB4+
K 2700	08.04–12.06	UB4+
K 2700 [SD]	04.98–08.04	UB4+
K 2900	05.07 →	UB4+
Magentis [GD]	09.00–12.05	UB8+
Mentor II [FX]	01.01–08.04	UB4+
Mentor II Hatchback [FX]	01.01–08.04	UB4+
Mohave	01.09 →	UB1+
Pregio [TB]	02.97–12.12	UB4+
Pro Cee'd [ED/FF2]	10.07–06.09	UB9+
Rio [DC]	07.00–02.05	UB4+
Rio Kombi [DC]	09.02–02.05	UB4+
Sephia I [FA]	01.92–12.00	UB4+
Sephia I Hatchback [FA]	09.96–12.00	UB4+
Shuma I [FB]	01.98–12.00	UB4+
Shuma I Hatchback [FB]	01.98–12.00	UB4+
Shuma II [FB]	01.01–08.04	UB4+
Shuma II Hatchback [FB]	01.01–08.04	UB4+
Sorento [XM]	09.09 →	UB1+
Soul [AM; PS]	02.09 →	UB1+
Spectra	01.01–12.09	UB5+





KIA

Sportage [JA]	05.93–08.04	UB3+
Sportage [JE]	09.04–05.10	UB2+

LANCIA

Delta [844]	07.08–12.14	UB9+
Kappa Berlina [838]	11.94–12.00	UB1+
Kappa Coupé [838]	04.97–06.00	UB1+
Kappa Station Wagon [838]	11.94–12.00	UB1+
Lybra Berlina [839]	10.99–11.06	UB8+
Lybra Station Wagon [839]	10.99–11.06	UB8+
Musa [184]	10.04–01.06	UB2+
Y [840]	01.96–06.03	UB2+
Ypsilon [843]	06.03–11.11	UB2+

LAND ROVER

Discovery III	09.04–08.09	UB8+
Discovery IV	09.09 →	UB8+
Freelander I [LN]	09.97–10.06	UB8+
Freelander II [LF]	10.06–11.14	UB9+
Range Rover II	09.94–08.02	UB8+
Range Rover IV [LG]	02.13–12.16	UB1+
Range Rover Sport I [LS]	03.05–08.13	UB8+

LEXUS

ES [V]	03.06–09.12	UB1+
GS [S1]	03.93–08.97	UB4+
GX 470 [J1]	11.02–08.09	UB8+
IS [E1]	01.99–07.05	UB7+
IS [E2]	08.05–04.13	UB8+
IS F [E2]	12.07–05.14	UB8+
IS Wagon [E1]	07.01–07.05	UB7+
LX [J1]	01.98–08.07	UB3+

MASERATI

420	01.87–12.01	UB3+
430	02.88–12.01	UB3+
Biturbo	03.89–12.01	UB3+
Karif	04.88–12.01	UB3+

MAZDA

2 [DY]	02.03–06.07	UB2+
3 [BK]	07.03–12.08	UB4+
3 [BL]	12.08–12.13	UB1+



MAZDA

3 Hatchback [BK]	07.03–12.08	UB4+
3 Hatchback [BL]	12.08–12.13	UB1+
323 [BJ]	05.98–09.03	UB4+
323 F Hatchback [BA]	05.94–07.98	UB4+
323 Hatchback [BA]	06.94–09.00	UB4+
323 Hatchback [BG]	03.91–05.96	UB4+
323 Hatchback [BJ]	06.98–09.03	UB4+
323 Sedan [BA]	06.94–06.98	UB4+
323 Sedan [BG]	06.89–02.97	UB4+
6 Fastback [GG/GY]	04.02–08.08	UB7+
6 Fastback [GH]	08.07–12.12	UB2+
6 Sedan [GG/GY]	02.02–08.07	UB7+
6 Sedan [GH]	08.07–12.12	UB2+
6 Wagon [GH]	12.07–12.12	UB2+
6 Wagon [GY]	06.02–12.07	UB7+
626 [GE]	08.91–03.97	UB5+
626 [GF]	05.97–07.02	UB4+
626 Fastback [GF]	08.99–04.02	UB4+
626 Hatchback [GE]	09.91–06.97	UB5+
626 Hatchback [GF]	04.97–07.02	UB4+
626 Wagon [GV]	03.92–10.97	UB3+
626 Wagon [GW]	10.97–04.02	UB4+
CX-3 [DK]	02.15 →	UB4+
MPV [LV]	07.94–04.99	UB8+
MX-3 [EC]	11.93–02.98	UB4+
MX-6 [GE]	07.91–07.98	UB3+
Premacy [CP]	03.99–05.05	UB2+
RX-7 Coupé [FD]	01.92–02.96	UB3+
RX-8 [FE/SE]	04.03–04.12	UB6+
Tribute [EP]	02.01–09.09	UB3+
Xedos-6 [CA]	01.92–02.99	UB4+
Xedos-9 [TA]	07.93–11.02	UB4+

MERCEDES-BENZ

Citan	07.12 →	UB8+
Serie A [176]	06.12–06.15	UB9+
Serie CLA [117]	12.12–06.15	UB9+
Serie CLA Shooting Brake [117]	01.15–06.15	UB9+
Serie GLA [156]	10.13–06.15	UB9+
Serie GLK [204]	06.08–01.14	UB7+
Serie ML [163]	03.98–06.05	UB8+
Serie SLK [170]	09.96–03.04	UB8+





mitsubishi

3000 GT	06.92–12.00	UB5+
Canter [FE]	10.96–10.00	UB3+
Carisma [DA]	05.96–12.03	UB5+
Carisma Hatchback [DA]	05.95–12.03	UB5+
Colt [CJ]	11.95–06.03	UB4+
Galant [E5...8]	11.92–10.96	UB4+
Galant [EA]	10.96–05.03	UB4+
Galant Fortis Sportback	12.08–12.09	UB2+
Galant Hatchback [E5...8]	11.92–10.96	UB4+
Galant Station Wagon [EA]	10.96–09.02	UB4+
L 200 [K6/K7]	01.96–12.07	UB3+
L 200 [KA,KB]	11.09 →	UB4+
L 200 [KB]	12.05–10.09	UB4+
L 200 [KL, KK]	02.15 →	UB4+
L 200 Forte [K7]	01.96 →	UB3+
Lancer [C6/C7]	04.88–07.95	UB6+
Lancer [CA/CB/CD]	12.91–12.96	UB6+
Lancer [CK/CP/CN]	11.95–05.01	UB4+
Lancer [CY/CZ]	03.07 →	UB2+
Lancer Hatchback [C6/C7]	06.92–07.95	UB6+
Lancer Sedan [CA/CB/CD]	01.93–12.96	UB6+
Lancer Sedan [CK/CP/CN]	05.96–05.01	UB4+
Lancer Sportback [CX]	07.08 →	UB2+
Lancer Station Wagon [CA/CB/CD]	06.92–09.00	UB6+
Outlander [CU]	02.03–09.07	UB7+
Pajero [V]	12.90–06.00	UB3+
Pajero [V60,V70]	02.00–08.06	UB3+
Pajero [V80,V90]	09.06 →	UB8+
Pajero Cabrio [V]	12.90–05.01	UB3+
Pajero IO	03.98–06.00	UB3+
Pajero Pinin [H]	10.99–02.06	UB3+
Pajero Sport [K]	07.96–02.09	UB3+
Pajero Sport [KH]	07.08 →	UB4+
Pajero Sport [KS]	12.15 →	UB4+
Space Runner	06.91–08.02	UB4+
Space Star [DG]	06.98–12.04	UB4+

NISSAN

200 SX [S13;S14]	09.88–12.99	UB3+
300 ZX [Z32]	01.90–08.96	UB5+
350 Z [Z33]	12.03–04.09	UB6+
350 Z Cabriolet [Z33]	09.03–04.09	UB6+
350 Z Coupé [Z33]	09.02–04.09	UB6+
Almera Hatchback [N15]	07.95–04.00	UB4+
Almera Sedan [N15]	07.95–04.00	UB4+
Cabstar [F24]	09.06 →	UB3+
Cube [Z12]	08.09–03.11	UB3+
Kubistar [X76]	07.03–03.09	UB3+
Maxima QX [A32]	10.94–01.00	UB5+



NISSAN

Micra [K11E]	08.92–10.02	UB6+
Micra [K12E]	11.02–10.10	UB4+
Micra CC [K12E]	09.05–10.10	UB4+
Navara [D22]	06.00 →	UB3+
Navara [D23M]	11.15 →	UB2+
Navara [D40;D40M;D40T]	05.05 →	UB1+
NP200	10.08 →	UB3+
NP300 [D22]	09.08 →	UB3+
Pathfinder [R50]	10.97–10.04	UB8+
Pathfinder [R51]	01.05–11.14	UB1+
Patrol [260]	04.89–12.05	UB3+
Patrol GR [Y60]	09.88–09.97	UB3+
Patrol GR [Y61]	10.97–03.10	UB3+
Pickup [D21]	08.87–02.98	UB3+
Pickup [D22]	02.97 →	UB3+
Primera Hatchback [P10E]	06.90–06.96	UB4+
Primera Hatchback [P11E]	06.96–12.01	UB5+
Primera Sedan [P10E]	06.90–06.96	UB4+
Primera Sedan [P11E]	06.96–12.01	UB5+
Primera Wagon [P11E]	01.98–12.01	UB5+
Primera Wagon [W10]	07.90–12.97	UB4+
Pulsar [N15]	01.95–08.00	UB6+
Pulsar Hatchback [N15]	01.95–08.00	UB6+
Sunny Hatchback [N14]	10.90–05.95	UB4+
Sunny Liftback [N14]	10.90–05.95	UB4+
Sunny Sedan [N14]	10.90–05.95	UB4+
Sunny Wagon [Y10]	11.90–03.00	UB4+
Teana [J31;L41F]	02.03 →	UB1+
Terrano [HS]	10.13–09.14	UB3+
Terrano I	11.88–08.95	UB3+
Terrano I [WD21]	09.95–12.06	UB5+
Terrano II [R20]	02.93 →	UB5+
Trade	03.87–12.00	UB3+
X-Trail [T30]	10.00–08.07	UB2+
X-Trail [T31]	04.07–12.14	UB2+

OPEL

Adam	03.13 →	UB10+
Agila [A]	06.00–02.08	UB6+
Antara	05.06 →	UB2+
Arena	03.98–08.01	UB3+
Astra [G]	09.97–07.09	UB6+
Astra [H]	03.04–08.13	UB7+
Astra Cabrio [G]	09.97–08.05	UB6+
Astra Caravan [G]	09.97–07.09	UB6+
Astra Caravan [H]	08.04–08.13	UB7+





OPEL

Astra Classic [F]	09.97–08.02	UB6+
Astra Classic Caravan [F]	09.97–08.02	UB6+
Astra Coupé [G]	09.97–02.05	UB6+
Astra GTC [H]	03.05–09.09	UB7+
Astra TwinTop [H]	09.05–10.10	UB7+
Calibra	06.90–03.97	UB3+
Corsa [C]	09.00–09.06	UB6+
Corsa [D]	07.06–08.15	UB10+
Corsa [E]	10.14 →	UB10+
Frontera [A;B]	09.91–09.04	UB3+
Monterey [A]	09.91–12.97	UB3+
Omega [B]	09.93–09.03	UB1+
Signum	05.03–09.08	UB1+
Tigra TwinTop [B]	06.04–12.09	UB6+
Vectra [A]	09.88–08.95	UB3+
Vectra [B]	09.95–09.03	UB3+
Vectra [C]	09.01–10.08	UB1+
Vectra Caravan [B]	09.95–09.03	UB3+
Vectra Caravan [C]	09.03–10.08	UB1+

PEUGEOT

106 [S1]	09.91–04.96	UB6+
106 [S2]	07.95–05.05	UB6+
2008	03.13 →	UB10+
208	01.12 →	UB10+
306 [N3]	01.93–04.97	UB8+
306 [N5]	05.97–10.03	UB8+
306 Break [N5]	05.97–03.02	UB8+
306 Cabriolet [N3;N5]	01.93–10.03	UB8+
308 II [T9]	07.13 →	UB9+
308 SW II [T9]	01.14 →	UB9+
Boxer [U3]	02.94–02.02	UB8+
Boxer [U5]	02.02–05.06	UB8+
Partner [B9]	05.08 →	UB10+
Partner [M4]	07.96–08.02	UB8+
Partner [M5]	09.02–10.11	UB8+
Ranch [M4]	07.97–08.02	UB8+

RENAULT

19 [X53]	09.88–12.01	UB3+
Clio I [X57]	03.94–02.98	UB3+
Clio II [BB./CB./SB.]	03.98–05.09	UB4+
Duster [HS]	10.11–09.14	UB3+
Fluence [L38]	11.09 →	UB2+
Kangoo I [FC./KC.]	10.97–12.07	UB3+
Kangoo II [FW./KW.]	01.08 →	UB8+
Koleos [HY.]	09.08 →	UB9+
Laguna I [B56; 556]	01.94–03.01	UB1+
Laguna I Grandtour [A56; K56; S56]	02.95–02.01	UB1+
Latitude	09.10 →	UB2+
Logan I [LS]	07.04 →	UB3+



RENAULT

Logan II [L8]	08.12–03.15	UB5+
Logan MCV [KS/FS]	01.07 →	UB3+
Mégane I [X64]	01.96–10.02	UB8+
Mégane I Cabrio [X64]	09.96–09.03	UB8+
Mégane I Classic [X64]	09.96–09.03	UB8+
Mégane I Coupé [X64]	01.96–10.02	UB8+
Mégane I Grandtour [X64]	07.98–09.03	UB8+
Sandero I [BS]	12.09 →	UB3+
Sandero II [B8]	12.14–03.15	UB5+
Scénic I [JA.]	01.96–04.03	UB2+
Symbol [L8]	03.13–03.15	UB5+
Symbol [LB]	10.99–10.07	UB4+
Thalia [LB]	10.99–10.07	UB4+
Trafic I	09.80–05.01	UB3+

ROVER

45	02.00–05.05	UB6+
75	01.99–05.05	UB8+
75 Tourer	01.01–05.05	UB8+
Serie 400	09.91–03.00	UB6+
Serie 400 Coupé	01.97–12.98	UB6+
Serie 400 Tourer	09.91–03.00	UB6+
Serie 600	04.93–09.00	UB8+
Serie 800	10.91–09.99	UB3+

SAAB

900 II	09.93–10.98	UB5+
900 II Cabrio	03.94–10.98	UB5+
900 II Coupé	03.94–10.98	UB5+
9000	12.85–12.98	UB5+
9-3 [9400]	03.98–09.02	UB5+
9-3 Cabriolet [9400]	03.98–08.03	UB5+
9-3 Coupé [9400]	03.98–08.03	UB5+

SEAT

Cordoba [6K2]	09.93–12.02	UB4+
Cordoba [6L2]	09.02–01.06	UB4+
Cordoba Vario [6K5]	04.97–08.03	UB4+
Ibiza [6K1]	03.93–05.02	UB4+
Ibiza [6L1]	09.01–01.06	UB4+
Inca [6K9]	11.95–06.03	UB6+
Leon [1M1]	10.98–06.06	UB4+
Toledo [1L2]	05.91–03.99	UB3+
Toledo [1M2]	10.98–07.04	UB4+





SKODA

Fabia [6Y2]	09.99–03.08	UB4+
Fabia Combi [6Y5]	12.99–12.07	UB4+
Fabia Sedan [6Y3]	09.99–12.07	UB4+
Favorit	07.93–12.98	UB3+
Felicia [6U1]	10.94–08.01	UB3+
Felicia Combi [6U5]	10.94–08.01	UB3+
Felicia Fun [6UF]	08.96–03.01	UB4+
Forman	10.90–12.95	UB3+
Octavia [1U2]	09.96–12.10	UB4+
Octavia [1Z3]	05.04–06.13	UB1+
Octavia Combi [1U5]	10.96–12.10	UB4+
Octavia Combi [1Z5]	05.04–06.13	UB1+
Pick-Up [6U7,787]	09.91–03.01	UB3+
Superb [3T4]	03.08–05.15	UB9+
Superb [3U4]	12.01–03.08	UB5+
Superb Combi [3T5]	03.09–05.15	UB9+
Yeti [5L7]	05.09 →	UB9+

SMART (MCC)

Fortwo Cabrio [450]	02.04–03.07	UB5+
Fortwo Coupé [450]	02.04–03.07	UB5+
Roadster [452]	04.03–11.05	UB6+
Roadster Coupé [452]	04.03–11.05	UB6+
Smart Cabrio [450]	03.00–01.04	UB5+
Smart Coupé [450]	07.98–01.04	UB5+

SSANGYONG

Actyon	10.05 →	UB4+
Actyon Sports	03.07 →	UB4+
Korando [CK]	07.10 →	UB2+
Korando C	02.11 →	UB2+
Kyron	05.05 →	UB7+
Musso [MJ]	07.93–12.05	UB6+
Rexton	09.01 →	UB3+
Rexton II	10.08 →	UB3+
Rexton W	06.12 →	UB3+
Rodius II	05.13 →	UB2+
Tivoli	07.15 →	UB2+
XLV	04.16 →	UB2+

SUBARU

BRZ [Z10]	01.12 →	UB8+
Forester [SF]	01.97–05.02	UB4+
Forester [SG]	06.02–11.07	UB4+
Impreza [G12/G22]	06.07–12.11	UB2+
Impreza Kombi [GC,GF]	01.93–09.00	UB4+
Impreza Sedan [G12]	06.07–12.11	UB2+
Impreza Sedan [GC,GF]	01.93–09.00	UB4+
Impreza Sports Wagon	11.92–07.00	UB4+
Justy [MA]	10.95–09.96	UB4+
Justy [MS]	10.96–08.03	UB4+
Legacy [BC/BF/BJ]	01.89–12.95	UB6+
Legacy Kombi [BD/BG]	01.94–11.98	UB4+



SUBARU

Legacy Kombi [BE/BH]	10.98–06.03	UB8+
Legacy Outback [BD/BG]	01.96–12.99	UB4+
Legacy Outback [BE/BH]	10.98–06.03	UB8+
Legacy Sedan [BD/BG]	01.94–03.99	UB4+
Legacy Sedan [BE/BH]	10.98–06.03	UB8+

SUZUKI

Baleno [WB32, WB42]	03.16 →	UB4+
Baleno Hatchback	04.95–09.05	UB6+
Baleno Sedan	04.95–09.05	UB6+
Baleno Wagon	08.96–09.07	UB6+
Escudo	05.05 →	UB3+
Grand Vitara	03.98–09.05	UB3+
Grand Vitara [JT]	10.05 →	UB3+
Grand Vitara Cabrio	03.98–03.08	UB3+
Ignis [MF]	10.16 →	UB4+
Kizashi	10.09 →	UB1+
Liana Hatchback	03.01–04.08	UB7+
Liana Sedan	04.02–12.07	UB7+
Swift [Z]	11.14 →	UB4+
Swift Hatchback [A2L]	05.17 →	UB6+
Swift Hatchback [AZH, AZG]	09.10 →	UB4+
Swift Hatchback [MA]	03.96–12.04	UB4+
Swift Hatchback [MZ/EZ]	11.04 →	UB4+
Swift Sedan [EA]	01.91–09.95	UB6+
Swift Sedan [MA]	03.96–12.04	UB4+
Swift Sedan [Z]	11.04 →	UB4+
Vitara [LY]	02.15 →	UB2+
Wagon R+ [EM]	10.96–05.00	UB6+
Wagon R+ [MM]	05.00–08.08	UB6+

TOYOTA

Avalon	09.99–08.04	UB2+
Avensis [T22]	10.97–01.03	UB4+
Avensis [T25]	01.03–11.08	UB2+
Avensis Liftback [T22]	10.97–01.03	UB4+
Avensis Liftback [T25]	01.03–11.08	UB2+
Avensis Wagon [T22]	10.97–01.03	UB4+
Avensis Wagon [T25]	01.03–11.08	UB2+
Camry [V1]	06.91–08.96	UB4+
Camry [V2]	06.96–08.01	UB4+
Camry [V3]	08.99–01.06	UB8+
Camry [V4, V40]	01.06 →	UB1+
Camry Wagon [V1]	03.92–08.96	UB4+
Carina E Liftback [T19]	02.92–10.97	UB4+
Carina E Sedan [T19]	02.92–10.97	UB4+
Carina E Wagon [T19]	11.92–10.97	UB4+
Celica Cabrio [T20]	08.94–05.99	UB4+
Celica Liftback [T20]	11.93–08.99	UB4+
Corolla [E10]	05.92–08.98	UB6+
Corolla [E11]	05.95–08.02	UB6+





TOYOTA

Corolla [E12]	08.00–08.08	UB7+
Corolla [E12]	10.02–08.08	UB2+
Corolla Hatchback [E10]	05.92–04.97	UB6+
Corolla Hatchback [E11]	05.97–07.01	UB6+
Corolla Hatchback [E12,JTD]	09.02–12.06	UB7+
Corolla Hatchback [E12,SB1]	11.01–12.07	UB7+
Corolla Hatchback [E12]	11.01–11.06	UB2+
Corolla Liftback [E10]	05.92–05.95	UB6+
Corolla Liftback [E11]	05.97–11.01	UB6+
Corolla Sedan [E10]	05.92–08.97	UB6+
Corolla Sedan [E11]	05.95–08.02	UB6+
Corolla Wagon [E10]	05.92–04.97	UB6+
Corolla Wagon [E11]	04.97–09.01	UB6+
Corolla Wagon [E12]	08.00–02.07	UB2+
Dyna	10.00 →	UB3+
Fortuner	01.05 →	UB4+
GT86	04.12 →	UB8+
Hiace [KLH]	08.01 →	UB5+
Hiace [LXH,RCH]	08.96–05.09	UB5+
Hiace Van [LH,LXH,ZH]	08.96–02.06	UB5+
Hiace Wagon [LH,ZH]	08.96–02.06	UB5+
Highlander	09.00–08.07	UB7+
Hilux [N15,N25,N26,N35]	07.05 →	UB4+
Hilux [Raider]	05.05 →	UB4+
Hilux Vigo [TGN16; TGN26]	08.04 →	UB4+
iQ	11.08–05.14	UB4+
Land Cruiser [J12]	09.02–08.09	UB8+
Land Cruiser Prado [J12]	09.02–09.09	UB8+
MR2 Cabrio [W3]	12.99–05.06	UB6+
Paseo [L5]	08.95–08.99	UB6+
Picnic	09.96–05.01	UB2+
Picnic	08.03 →	UB2+
Prius [W11]	09.00–08.03	UB2+
RAV4 [A1]	04.94–08.00	UB6+
RAV4 [A2]	05.00–01.06	UB1+
RAV4 [A3]	11.05–11.12	UB2+
RAV4 Cabrio [A1]	11.95–08.00	UB6+
Sequoia	09.07 →	UB3+
Sienna	01.10 →	UB1+
Solara	09.98–08.03	UB8+
Solara	09.03–08.08	UB1+
Starlet [P9]	01.96–07.99	UB6+

VOLVO

440	09.88–07.97	UB5+
460	03.90–07.97	UB5+
480 [E12]	08.88–12.96	UB5+
740	09.90–07.95	UB3+
850	09.91–07.98	UB5+
850 Kombi	09.91–07.98	UB5+
940	09.90–10.98	UB3+
960	08.90–07.98	UB5+
C70 Coupé	01.97–07.02	UB5+
C70 I Cabrio	02.98–03.06	UB5+
S40 I	09.95–01.04	UB3+
S70	01.97–07.00	UB5+
S90 I	01.97–05.98	UB5+



VOLVO

V40 I	01.95–08.04	UB3+
V70 I	01.97–03.00	UB5+
V90 I	01.97–07.98	UB5+

VW (VOLKSWAGEN)

Bora [1J2]	09.98–05.05	UB4+
Bora Variant [1J6]	09.98–05.05	UB4+
Caddy [2C]	09.10–05.15	UB9+
Caddy [2K]	11.06–08.10	UB9+
Caddy [9K9]	11.95–06.03	UB4+
Caddy [SA]	05.15–05.17	UB9+
Caddy Pickup [9U7]	06.96–12.00	UB4+
California T4 [70,7D]	09.90–06.03	UB5+
Caravelle T4 [70,7D]	09.90–06.03	UB5+
Corrado [50]	09.88–07.95	UB3+
Eos [1F7,1F8]	05.06–08.15	UB9+
Eurovan [70]	09.91–08.01	UB5+
Golf III [1H1]	11.91–12.97	UB4+
Golf III Cabriolet [1E7]	09.93–04.98	UB4+
Golf III Variant [1H5]	07.93–02.99	UB4+
Golf IV [1J1]	10.97–06.05	UB4+
Golf IV Cabriolet [1E7]	04.98–06.02	UB4+
Golf IV Variant [1J5]	05.99–06.06	UB4+
Golf V [1K1]	10.03–10.05	UB1+
Golf V [1K1]	11.05–11.08	UB9+
Golf V Variant [1K5]	05.07–07.09	UB9+
Golf VI [5K1]	10.08–11.12	UB9+
Golf VI Variant [AJ5]	06.09–04.13	UB9+
Jetta [1K2]	01.05–11.05	UB1+
Jetta [1K2]	12.05–10.10	UB9+
Lupo [6X1]	06.03–07.05	UB3+
Multivan T4 [70,7D]	09.90–06.03	UB5+
Passat [35I,3A2]	04.88–03.97	UB5+
Passat [362]	08.10–11.11	UB9+
Passat [3B2]	10.96–11.00	UB5+
Passat [3B3]	10.00–05.05	UB5+
Passat [3C2]	03.05–11.10	UB9+
Passat CC [357]	05.08–11.11	UB9+
Passat Variant [35I,3A5]	04.88–03.97	UB5+
Passat Variant [3B5]	01.97–11.00	UB5+
Passat Variant [3B6]	10.00–05.05	UB5+
Passat Variant [3C5]	08.05–11.10	UB9+
Passat Variant [365]	08.10–11.11	UB9+
Polo [6N1]	10.94–12.99	UB3+
Polo [6N2]	07.98–09.01	UB3+
Polo [9N1]	09.01–06.05	UB4+
Polo Classic [6V2]	11.95–09.01	UB4+
Polo Playa [9V4]	10.98–10.02	UB6+
Polo Variant [6V5]	05.97–09.01	UB4+
Scirocco [137,138]	08.08 →	UB9+
Touran [1T2]	11.06–05.10	UB9+
Touran [1T3]	05.10–05.15	UB9+
Transporter T4 [70,7D]	09.90–06.03	UB5+
Vento [1H2]	11.91–12.97	UB4+



**MTS MarkenTechnikService
GmbH & Co. KG**

~~Benzstr. 1~~

~~76185 Karlsruhe – Germany~~

www.mts-gruppe.com

Intertec Polska Sp. z o.o.

Stara Wieś ul. Grodziska 22

05-830 Nadarzyn – Poland

www.intertec-polska.pl

Tegro AG

Ringstr. 3

8603 Schwerzenbach – Switzerland

www.tegro.ch

www.mts-gruppe.com



02/2018