





- |                                  |                              |
|----------------------------------|------------------------------|
| (D) Montageanleitung             | (GB) Assembly instructions   |
| (FR) Notice de montage           | (IT) Istruzioni di montaggio |
| (NL) Handleiding voor de montage | (PL) Instrukcja montażu      |
| (CZ) Montážní návod              | (SK) Návod na montáž         |
| (HU) Szerelési útmutató          | (RO) Instrucțiuni de montaj  |
| (TR) Montaj talimatı             | (RU) Инструкция по монтажу   |



0  
10  
20  
30  
40  
50  
60  
70  
80  
90  
100  
110  
120  
130  
140  
150  
160  
170  
180  
190  
200

Service • Assistenza • Dienstverlening • Serwis  
Servis • Szerviz • Сервисная служба


Name • Nom • Nome • Naam •  
Nazwa • Jméno • Název • Név •  
Denumire • İsim • Название

Nr. • No. • N° • Номер • Č • Sz
2988 8244


Tur • Type • Тип • Típus • Tipo •  
Typ

|                             |                             |                           |                              |                           |
|-----------------------------|-----------------------------|---------------------------|------------------------------|---------------------------|
| <b>A</b><br><br>M8x20    x4 | <b>B</b><br><br>M8x20    x4 | <b>C</b><br><br>Ø22    x4 | <b>D</b><br><br>Ø10mm    x16 | <b>E</b><br><br>4mm    x1 |
|-----------------------------|-----------------------------|---------------------------|------------------------------|---------------------------|

-2-




1




|                                                                                                                           |                                                                                                                         |
|---------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------|
| <b>A</b><br><br><b>M8x20</b> <b>x4</b> | <b>E</b><br><br><b>4mm</b> <b>x1</b> |
|---------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------|


2



3



4




|                                                                                                                             |                                                                                                                           |
|-----------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------|
| <b>B</b><br><br><b>M8x20</b> <b>x4</b> | <b>E</b><br><br><b>4mm</b> <b>x1</b> |
|-----------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------|

5

C



Ø22 x4




6


D



Ø10 x16



7



8

