






Art. Nr. 6154 5156

LKZ 41164



- | | |
|----------------------------------|------------------------------|
| (D) Montageanleitung | (GB) Assembly instructions |
| (FR) Notice de montage | (IT) Istruzioni di montaggio |
| (NL) Handleiding voor de montage | (PL) Instrukcja montażu |
| (CZ) Montážní návod | (SK) Návod na montáž |
| (HU) Szerelési útmutató | (RO) Instrucțiuni de montaj |
| (TR) Montaj talimati | (RU) Инструкция по монтажу |



0	A 000151  8x35 x10	B 172324  4x50 x20	C 134613  x4	D 000083  M6x12 x8	E 010942  4x16 x32	F 113834  x4
10	G 230041  22x16 x4	H 208944  x4	I 213618  M8 x4	J 000112  x4	K 000762  3.5x13 x16	L 290072  x1
20						
30						
40						
50						
60						
70						
80						
90						
100						




N	LxBxH (mm)	Qty	✓	N	LxBxH (mm)	Qty	✓
1	1019x710x16	1		3	910x300x22	2	
2	1019x395x16	1		4	2020x210x22	2	
				5	1900x48x35	2	

Service - Dienstverlening - Serwis - Servis - Сервисная служба


Name - Naam - Nazwa - Isim - Название

Nr. - No. - Номер


Typ - Type - Тип - Тип



1



C
134613



x4

E
010942




4x16


x16

2

x2



A
000151




8x35

x10

3

x2



F

113834



x4

K

000762




3.5x13

x8


4

x2



B



172324





4x50

x12

5



6



134613
C

x4

000083
D


M6x12

x8

010942
E

4x16

x16



G
230041

22x16

x4

H
208944

x4


I
213618

M8

x4

J
000112

x4



B		4x50
172324		x8
L		luettenhut
290072		x1

